



ESCO PRODUCTS

SERVICE & SOLUTIONS

(800) 966-5514

www.esco-inc.com

info@esco-inc.com

PROPER LEVEL MONITOR INSTALLATION

When installing the **Esco Oil Sight Glass and Level Monitor**, proper vertical alignment cannot be attained by threading the nipple directly into the drain valve. Installers compensate by over-tightening the connection to move the OSGL into the correct upright position.

To help Esco's customers to mount their levelers correctly, the installation guidelines on the label of every OSGL has been updated to include the use of a union.



This over-tightening can lead to cracks in the acrylic and compromise the effectiveness of the OSGL. Esco suggests using a Union when installing the OSGL.



Responding to customer needs to view the levels in larger oil reservoirs Esco began to manufacture 15", 18" and 24" Oil Sight Glass Level Monitors. Esco recommends that on Level Monitors longer than 12" a support bracket should be utilized for stability.

Please contact Esco Products with installation or technical questions. We are here to help you!

VISIT US ON THE WEB:

- Download chemical resistant charts
- Read case studies
- Download the Oil Sight Glass Product Line brochure
- Read FAQs
- Client List



Problem solved! Proper vertical alignment is easily attained with the use of a union and there is no longer a threat of over-tightening the connection and cracking the Level Monitor.